

MAX. VOC 350 g/L This product meets SCAQMD Rule 1113-Architectural coatings; Faux Finishing category -Decorative Coatings

> Modern Masters Inc. Valencia. CA 91355 USA (800) 942-3166 modernmasters.com

© 2015. Modern Masters Inc. Made in USA





Metallic Paint

COLLECTION Pre-Mixed Metallic Paint Color

Water Base

1 US Gal. / 3.78 L

Low VOC

PERFECT FOR: Hospitality Commercial/Retail Residential Corporate Offices Casinos Theme Parks

To view instructional videos, visit Modern Masters YouTube Channel

COVERAGE <i>COBERTURA</i>	Drying Time	58°F+
320-400	<u>Tiempo de Secado</u>	Recoat: 30 min. <i>Repintar: 30 minutos</i>
sq ft / gal <i>pies cuadrados / gal</i>	@ 70% RH	Dry Time: 1 hour <i>Tiempo de Secado: 1 hora</i>
See details in Coverage Characteristics	Temperature and humidity dependent	
Vea los detalles en características de cobertura	Dependiente de temperatura y humedad	

SURFACE PREPARATION: Follow standard practices and procedures for properly preparing surfaces for the application of water base latex paints. Surfaces must be free of dirt. oil and grease. Remove all loose, flaking or chalking surfaces. Do not apply over slick or glossy surfaces. Prime surfaces with a 100% acrylic latex primer (we recommend Zinsser's Bullseye® 1-2-3 primer/sealer) and allow to dry completely.

Coverage Characteristics: There are three levels of coverage/hide: Opague, Semi-Opague and Sheer. Opaque colors have excellent hide: two coats are recommended for best results. Semi-Opaque colors have good hide; three coats are recommended for best results. Sheer colors are translucent overcoats that give luster to traditional paints, other Metallic Paint colors or faux finishes. Check the side of the label for the coverage level.

APPLICATION METHODS: Metallic Paint can be brushed, rolled or sprayed onto any paintable properly primed, interior or exterior surface. Check the side label for hide and coverage characteristics. Always test the product before beginning a project. Do not apply on surface temperatures below 58°F/14°C or above 85°F/29°C. Stir well before use. Brushina: Use a high-guality brush recommende for water base semi-gloss latex paints Rolling: To roll add up to 16 fl. oz. /473 m Metallic Paint Extender to one gallon/3.78 of Metallic Paint. This extends the "wet-edge" time necessary to avoid lapping. Use the Modern Masters Metallic Paint Roller to apply Metallic Paint to large surfaces. Use a 4-inch "sausage roller" (e.g. Whizz[™]) with 1/2" nap for cutting in corners, ceilings and baseboards. Work in approximately 4' wide sections. Keep

a "wet-edge", finishing the surface by backrolling in one direction, ceiling to floor. This technique will minimize lap marks, properly orient the metallic particles and ensure a uniform finish. *Spraying:* To spray use HVLP gun or a conventional cup gun with the fluid and air supply from a pressure pot and compressor. Air pressure at the HVLP spray gun needs to be approximately 45 psi, with greater pressure in the tank. Note: Do not use turbine-type "air-compressors" to power the HVLP spray gun; do not use other types of spray guns (e.g. airless spray guns). If thinning is necessary add up to 16 fl. oz./473 ml of water per one gallon/3.78 L. Over thinning will result in loss of hide.

PROTECTIVE CLEAR COATING: In certain applications (e.g. exterior areas and interior high traffic areas) Metallic Paint should have Metallic Paint Collection MasterClear® UV Protective Clear Topcoat Satin or Semi-Gloss applied for washability, scuff resistance and abrasion resistance.

CLEAN UP: Clean brushes, rollers, tools and equipment with warm, soapy water immediately after use.

HANDLING & STORAGE: To avoid skinning. close container after each use. Keep lid tightly closed during storage. Protect from freezing If contents freeze, allow thawing at room temperature before use. Dispose of unused or unwanted product in accordance with local laws regulating water base coatings.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS. SUCH AS BRAIN

DAMAGE, ESPECIALLY IN CHILDREN PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

HEALTH & SAFETY: Avoid contact with eves Wash hands after use. Do not take internally When spraving or sanding wear an appropriate properly fitted respirator (NIOSH approved) during and after application. Follow respirator manufacturer's directions for respirator use

KEEP OUT OF REACH OF CHILDREN CONFORMS TO ASTM D4236

WARRANTY: This product will perform as claimed if directions are followed. Directions are as complete as possible, but cannot encompass all conditions, applications, techniques, and/or surfaces, which are beyond our control. Warranty is limited to replacement or refund value of product actually used, if such product proves defective within two years of manufacture. No other warranty is expressed or implied.

Visit modernmasters.com for Technical Data Sheets, Material Safety Data Sheets, Application Instructions and the latest information on all our specialty water base paints and coatings

The First Choice in Metallic Paint