



## **Invisible Clear Color Fluorescent Polyurethane Top Coat**

Water Base
Non-Yellowing
Color Balanced

SPECIFICALLY FORMULATED FOR MAXIMUM BRIGHTNESS UNDER BLACKLIGHT

1 US Ouart / 946 ml

## WILDFIRE FLUORESCENT PRODUCTS

Paint

Originally developed for the scenic studios in Hollywood to create dramatic visual effects for film, television, theme parks and other "high profile" amusement venues, Wildfire brand fluorescent products are the standard for the visual effects professional. Blacklight Modern Masters' latest breakthrough in fluorescent coatings technology is Wildfire Invisible Clear Color, a unique addition to the Wildfire family of brilliant, color balanced, UVactivated paints. Invisible Clear Color, when applied under normal lighting conditions, over any previously painted surface, appears to be a typical, low sheen, protective clear top coat. But, when UV blacklight is applied Wildfire Invisible Clear Color comes to life with the maximum color brilliance you've come to expect from Wildfire!

Where to Use Ideal for use on any properly prepared interior surface, including canvas, paper, plaster, metal, wood, plastic, masonry, fabric or any non-slick, non-oily substrate.

Surface Preparation Painted surface should be clean, dry and fully cured prior to application. Apply on a small test area to ensure the color and desired effect is achieved

Application Methods Product is ready to use, do not dilute with water. For best results apply with an airbrush, HVLP spray equipment artist brushes or varnish roller. Maximum brilliance is achieved over light colors. Do not use over slick or glossy surfaces. For total invisibility, apply one or two coats of Wildfire "SHEEN LEVELER" over the entire completed project. Do not apply when air and surface temperatures are below 50° F (10° C) or high humidity conditions exist. Optimal conditions are 60° F (16° C) to 80° F (27° C) and 30% to 60% relative humidity. Stir thoroughly before use, do not shake.

Coverage Invisible Clear Color covers approx. 50-60 sq. ft / quart 4.5-5.5 M<sup>2</sup> / 946ml. Dry Times Recoat time is approx. 1/2 hour. Dry time is approx. 1 hour. The dry time will vary with temperature and humidity. Cleanup Clean tools, brushes and equipment with warm, soapy water immediately after use. Promptly wipe up spills and splatters with a damp cloth.

Handling & Storage Store Invisible Clear Color out of direct sunlight To avoid skinning, close container after each use. Keep lid tightly closed during storage. Protect from freezing.

Health & Safety Ensure fresh air entry during application and drying. Avoid contact with eves, skin and clothing. If you experience eve watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate. properly fitted (NIOSH approved) respirator. Follow respirator manufacturer's directions for respirator use. Wash thoroughly after handling. Refer to product MSDS for additional health and safety information

First Aid If you experience difficulty in breathing, leave the area to obtain fresh air. Do not breathe dust Harmful if inhaled. If continued difficulty is experienced, get medical attention immediately.

## **KEEP OUT OF REACH OF CHILDREN** CONFORMS TO ASTM D4236

Modern Masters Inc. • Valencia, CA 91355 USA modernmasters.com • (800) 942-3166 • Made in USA

Wildfire® and its symbol are registered trademarks of Wildfire Lighting & Visual Effects Torrance, CA www.wildfirefx.com