


SATISFACTION GUARANTEED: If you are dissatisfied with this product, contact Rust-Oleum Product Support at 800-942-3166 for product replacement or a full refund of the purchase price. Refer to product number and batch code.

RUST-OLEUM CORPORATION

11 Hawthorn Pkwy., Vernon Hills, IL 60061 800-942-3166 modernmasters.com



Metallic Paint Collection



Exterior Satin Finish

Superior Durability | No Clear Coat Required

Weather Resistant



sq ft / gal



Drying Time

Recoat: 1-2 hours

Full Cure: 12-24 hours

Temperature and humidity dependent

Perfect for exterior surfaces such as window mullions and architectural features.

SURFACE PREPARATION: Follow standard practices and procedures for properly preparing surfaces for the application of water base latex paints. Surfaces must be free of dirt, oil and grease. Remove all loose, flaking or chalking surfaces. Do not apply over slick or glossy surfaces. Prime surfaces with Modern Masters Exterior Metallic Paint Primer (Warm Tone or Cool Tone). Refer to Technical Data Sheet for additional information.

APPLICATION METHODS: Exterior Metallic Paint can be brushed, rolled or sprayed onto any paintable, properly primed, interior or exterior surface. Check the side label for hide and coverage characteristics. Always test the product before beginning a project. Do not apply on surface temperatures below 58°F/14°C or above 85°F/29°C. Two coats are recommended for best results. Stir well before use. Brushing: Use a high-quality brush recommended for water base paints. Rollina: Use a high-quality roller with 3/8" nap. Work in approximately 4-foot wide sections, keeping a wet edge, cross roll to improve coverage, and finishing the surface by back-rolling in one direction, top to bottom. This procedure will minimize lap marks, ensure a uniform surface. **Spraying:** To spray

spray gun needs to be approximately 45 psi, with greater pressure in the tank. If thinning is necessary add up to 16 fl. oz./473 ml of water per one gallon/3.78 L. Over thinning will result in loss of hide. Refer to the technical data sheet for additional information on spray

CLEAN UP: Clean brushes, rollers, tools and equipment with warm, soapy water immediately after use.

HANDLING & STORAGE: To avoid skinning, close container after each use. Keep lid tightly closed during storage.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE. ESPECIALLY IN CHILDREN PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

HEALTH & SAFETY: Avoid contact with eves. Wash hands after use. Do not take internally. When spraying or sanding wear an appropriate, properly fitted respirator use a HVLP gun or a conventional cup gun (NIOSH approved) during and after with the fluid and air supply from a pressure application. Follow respirator manufacturer's pot and compressor. Air pressure at the HVLP directions for respirator use.

WARNING: Cancer and Reproductive Harm – www.P65Warnings.ca.gov.

KEEP OUT OF REACH OF CHILDREN

58°-85°F

WARRANTY: This product will perform as claimed if directions are followed. Directions are as complete as possible, but cannot encompass all conditions, applications. techniques, and/or surfaces, which are beyond our control. Warranty is limited to replacement or refund value of product actually used, if such product proves defective within two years of manufacture. No other warranty is expressed or implied.

Visit **modernmasters.com** for Technical Data Sheets, Safety Data Sheets, Application Instructions and the latest information on all our specialty water base paints and coatings.

MAX. VOC 350 q/L